DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-021416 Address: 333 Burma Road **Date Inspected:** 05-Jan-2011

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Geng Wei **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector Larry Viars was present during the times noted above for observations relative to the work being performed.

Bay 14-

This QA Inspector observed the following work in progress: Shielded Metal Arc Welding (SMAW) of OBG Segment 14E longitudinal diaphragm to bottom panel weld, SEG3019Y-053. ZPMC welder was identified as 043661. ZPMC QC was identified as.Wang Lu. ZPMC CWI was identified as Geng Wei. The welding appeared to be in conformance with welding procedure specification, WPS-345-SMAW-2G(2F)-FCM-Repair.

Flux Cored Arc Welding (FCAW) of OBG Segment 14E hinge plate to bottom panel weld, SEG3019L-1-001. ZPMC welder was identified as 068501. ZPMC QC was identified as Zhong Guo Hui. ZPMC CWI was identified as Geng Wei. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2233-ESA.

Caltrans QA observed ZPMC Ultrasonic Testing (UT) personnel performing UT of vertical shear plates to Bottom panel welds located on OBG Segment 14E.

Flux Cored Arc Welding (FCAW) of OBG segment 14E bottom panel stiffener to floor beam weld, SEG3019N-226. ZPMC welder was identified as 044824. ZPMC QC was identified as Wang Xu. ZPMC CWI was identified as Geng Wei. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2132-ESAB.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Shielded Metal Arc Welding (SMAW) of OBG Segment 14E floor beam stiffener to longitudinal diaphragm to weld, SEG3019L-1-321. ZPMC welder was identified as 067665. ZPMC QC was identified as Wang Xu. ZPMC CWI was identified as Geng Wei. The welding appeared to be in conformance with welding procedure specification, WPS-B-P-2214-TC-U4b-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation between QA and QC occurred this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150 0042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Viars,Larry	Quality Assurance Inspector
Reviewed By:	McClendon, Timothy	QA Reviewer